



STEP 1

1. Hot Tapping Tee Sleeve installation.
2. Weld Perimeter of tee sleeve.




STEP 2

1. Thrust Block and Sluice Valve installation.



STEP 3

1. Mount Hot Tapping machine on sluice valve
2. Perform Hot Tapping machine.



STEP 4

1. Finally, Removal Hot Tapping machine.

