



STEP 5


1. Mount Linstop pluggger machine on temporary gate valve
2. Open Sluice valve and temporary gate valve
3. Perform Linstop plugging machin.
4. After perform linstop plugging machine, cut pipe and install ring flange.

**STEP 6**

1. Blank flange at cutting pipe.
2. Removal the linstop plugging machine
3. installation of the completion plug machine to remove all the temporary gate valve

**STEP 7**

1. Removal the completion plug machine and completion plug will belocked with set screw from the side of flange of linstop tee sleeve.
2. Then remove the temporary gate valve.

**STEP 8**

1. Finally, installation of blank flanges with bolt and nut.

